

Supported Models	Release Date	Printer Firmware		LETATWIN PC EDITOR PRO App (PC Software)	
		Version	Modifications	Version	Modifications
LM-3000PRO	26.04.22	1.3	Fixed an issue with print distance compensation when "Off" is selected in "Pitch cutting." Added a feature to automatically create a root folder on a USB drive. Fixed the cumulative print distance monitoring item.	1.1.0.0	There are no new features or fixes in this release.
LM-3000PRO	26.05.14	1.4	Extended the pitch length of the tape and marking strips.	1.2.0.0	Extended tape and label pitch lengths. Fixed an issue with loading LMF files. Fixed an issue with copying and pasting in drop-down lists. Fixed an issue with inch display. Fixed an issue caused by unsupported characters when saving CSV files.
LM-3000PRO	26.07.30	1.4	There are no new features or fixes in this release.	1.2.1.0	Fixed the user manual (TW model). Fixed version number notation (all models).
LM-3000PRO	26.09.02	1.5	Support for CE mark printing. Adjustment of heat input for sleeve printing.	1.3.0.0	Support for CE mark printing. Added method for specifying print areas. Support for inch as the default display unit (US model). Fixed a preview display issue when pitch length is set to "Auto". Prevented file insertion into higher-end models. Supported replacement of default values when inserting files. Reflects minimum pitch length when pitch length is set to "Auto".

*Please ensure that both the printer firmware and LETATWIN PC EDITOR PRO (PC Software) are updated to their latest versions.

*Updating the printer firmware takes about 20 minutes.

*Please ensure that both update files are saved to a USB drive when updating the printer firmware to version 1.5.